

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2022

Submitted Date:

08/08/2022

Document Number:

688312784

FIELD INSPECTION FORM

Loc ID 317106 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 81490
Name of Operator: ST CROIX OPERATING INC
Address: P O BOX 13799
City: DENVER State: CO Zip: 80201

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Crumley, Luke	(970) 324-0060	crumleypumping@gmail.com	
Melnychenko, Paul	(303) 489-9298	stcroixexp@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236381	WELL	PR	05/01/2019	OW	121-08871	STATE 2-16	PR

General Comment:

[Routine Field Inspection](#)

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: FWKO	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		

Comment:	bermed, shed, insulated		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 5			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	pump shed		Date:	
Corrective Action:			Date:	
Type: Progressive Cavity	# 1			
Comment:	electric		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	same earth berms as 500 bbl produced water tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		,
Comment:		fiberglass, netted			
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:		same earth berms as 2 other produced water tanks			
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	500 BBLs	STEEL AST		,
Comment:		one heated, one insulated (replace box cover on insulated tank)			
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Wells Served By Facilities Above					
API Number		AirsID			
121-08871		API Number		AirsID	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Location Construction

Location ID: 236381 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 236381 Type: WELL API Number: 121-08871 Status: PR Insp. Status: PR

Producing Well

Comment: [pr 5/1/2022 production is reported to COGCC database.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Berms	In Process					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action:

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action:

Date: _____

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action:

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type:	Netting Condition:	
Comment:	<input style="width:100%;" type="text"/>	
Corrective Action:	<input style="width:100%;" type="text"/>	
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<input style="width:100%;" type="text"/>	
Corrective Action:	<input style="width:100%;" type="text"/>	
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: _____ Lat: _____ Long: _____
Reference Point: _____	Other: _____	Length: _____ Width: _____
<u>Lining:</u>		
Liner Type:	Liner Condition:	
Comment:	<input style="width:100%;" type="text"/>	
Corrective Action:	<input style="width:100%;" type="text"/>	
<u>Fencing:</u>		
Fencing Type: <u>None</u>	Fencing Condition:	
Comment:	<input style="width:100%;" type="text"/>	
Corrective Action:	<input style="width:100%;" type="text"/>	
<u>Netting:</u>		
Netting Type:	Netting Condition:	
Comment:	<input style="width:100%;" type="text"/>	
Corrective Action:	<input style="width:100%;" type="text"/>	
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<input style="width:100%; color: blue;" type="text" value="The southern berms on the first pit eroded into bar ditch, did not transport to road or any drainages (see attached photo). Add stormwater BMP."/>	
Corrective Action:	<input style="width:100%;" type="text"/>	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688312872	St Croix State 2-16	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5823911