

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2022

Submitted Date:

08/09/2022

Document Number:

688312792

FIELD INSPECTION FORM

Loc ID 320674 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|--------------------------|---------------------------------|
| Leonard, Mike | | mike.leonard@state.co.us | |
| KPK | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 204420 | WELL | PR | 02/01/2022 | GW | 005-06505 | FRICK, VIOLA 32-2 | PR |

General Comment:

[Crypto Mining Equipment Inspection](#)

Location

Lease Road:

| | | | |
|--------------------|-----------------------|-------|------------|
| | Type Access | | |
| comment: | control weeds | | |
| Corrective Action: | Comply with Rule 606. | Date: | 08/23/2022 |

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------------------------------|-------|--|
| | Type WELLHEAD | | |
| Comment: | on the ground (see attached photo) | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|--|
| Comment: | 303-825-4822 | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| | | # | | corrective date |
|--------------------|--|-----|--|-----------------|
| Type: Bradenhead | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | <input style="width: 95%;" type="text"/> |
| Other (Content) | <input style="width: 95%;" type="text"/> |
| Other (Capacity) | <input style="width: 95%;" type="text"/> |
| Other (Type) | <input style="width: 95%;" type="text"/> |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 204420 Type: WELL API Number: 005-06505 Status: PR Insp. Status: PR

Producing Well

Comment: [pr 5/1/2022 reported as SI to COGCC database.](#)
[Form 4 Document #402924489 04 \(OBJ-VENT_FLARE\) -00](#)
[Attachment count: 3 IN PROCESS 2/25/2022 2/25/2022 KP KAUFFMAN COMPANY INC](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403130044 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5824043 |
| 688312880 | KPK Frick Viola 32-2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5824032 |