

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2022

Submitted Date:

08/10/2022

Document Number:

697601844

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
-, Marcom		primarycontractor@marcomllc.net	
Graber, Nikki		nikki.graber@state.co.us	
Gorka, Ray		RGorka@kpk.com	KPK environmental
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482598	SPILL OR RELEASE	AC			-	3 Farms Consolidation line	EI

General Comment:

This is an environmental inspection for Spill ID 482598 3 Farms Consolidation Line. Any corrective actions from previous forms in relation to spill ID 482598 that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment: Signage adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type STORAGE OF SUPL

Comment: Unused equipment and trash was left within the excavation.

Corrective Action: Comply with Rule 606.

Date: 08/04/2022

Overall Good:

Spills:

Type	Area	Volume			

In Containment: Yes

Comment: Excavation crews have removed visible impacted soil from the surface. Excavation below access valve (release point) pending.

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Fencing around the excavation is adequate.

Corrective Action:

Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 482598 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Excavation crews have removed visible impacted soil from the surface. Excavation below access valve (release point) pending.

Corrective Action:

Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403133715	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5827783
697601845	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5827770