

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/14/2022

Submitted Date:

08/19/2022

Document Number:

688312929

**FIELD INSPECTION FORM**

Loc ID 320777 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

13 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204893	WELL	PR	11/01/2019	OW	005-06978	MURPHY 5-2	PR

**General Comment:**

[Crypto Currency Mining Equipment Inspection](#)

Document #402927620 04 (OBJ-VENT\_FLARE) -00 Attachment count: 3 IN PROCESS 4/29/2022 4/29/2022. Gas Cap Plan is attached to this document. These documents must include current use of gas (e.g., Crypto mining, etc.). The generator is to use all the gas produced and gas to generator is to be metered.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	sign on ground		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels are weather worn, maintain labels.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	303-825-4822		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine, leaking fluid on plate, fix leak		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Electric genertor and Crypto Currency Mining Equipment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment: <a href="#">locked (see attached photo)</a>		Date:
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: <a href="#">Shed is locked. Pumper does the meter calibration and has date calibrated in field notebook.</a>		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment: <a href="#">on</a>		
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">same earth berms as crude oil tanks</a>				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		,
Comment: <a href="#">Tanks sounded mostly empty however the west tank was leaking oil at the bottom and the east tank was leaking fluid (see attached photos). Inspector called pumper who would check.</a>					

Corrective Action: <b>Verify with inspector that the tanks were checked and oil cleaned up and properly disposed of.</b>	Date: <u>08/26/2022</u>
--	-------------------------

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

<b>Wells Served By Facilities Above</b>	<b>AirsID</b>
API Number	API Number      AirsID
005-06978	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 204893 Type: WELL API Number: 005-06978 Status: PR Insp. Status: PR

**Producing Well**

Comment: [pr 6/1/2022 production is reported to COGCC database.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403142221	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5834851">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5834851</a>
688312930	KPK Murphy 5-2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5834838">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5834838</a>