

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD-66S94W /23SESE

Location ID: 323783



Photo #7549 from entrance to location.



Photo #7550 from entrance to location.

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD-66S94W /23SESE

Location ID: 323783



Photo #7551 from entrance to location.



Photo #7552 Multiple places with undesirable plant species.

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD-66S94W /23SESE

Location ID: 323783



Photo #7554 Multiple places with undesirable plant species



Photo #7556 Vent pipe on separator open ended.

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD-66S94W /23SESE

Location ID: 323783



Photo #7557 Multiple places with stained soils on location.



Photo #7558 Multiple places with stained soils on location.

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MEAD-66S94W /23SESE

Location ID: 323783



Network time is not synchronize
Local:Aug 24, 2022 at 1:13:55 PM MD



Network time is not synchronize
Local:Aug 24, 2022 at 1:12:52 PM MD

Photo #7559 Tank missing required information.

Photo #7555 Rill erosion occurring on North West side of location.