

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2022

Submitted Date:

08/23/2022

Document Number:

693507795

FIELD INSPECTION FORM

Loc ID 320458 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10694
Name of Operator: PROVIDENCE OPERATING LLC DBA POCO
Address: 16400 DALLAS PARKWAY SUITE 400
City: DALLAS State: TX Zip: 75428

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Grimes, Meghan		mgrimes@providence-energy.com	
Brown, Devin		dbrown@providence-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203817	WELL	PR	02/01/2021	GW	001-09377	ZARLENGO 24-4	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Placards on crude oil tank starting to fade may need to be replaced in near future		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Good Housekeeping:			
Type	OTHER		
Comment:	Netting on open top tanks inadequate		
Corrective Action:	Install or repair wildlife protection equipment. per rule 608 a (13)	Date:	09/23/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment piping, belt guard and fencing.		
Corrective Action:	Comply with rule 606	Date:	09/23/2022
Type	WEEDS		
Comment:	Weeds around well head and production equipment		
Corrective Action:	Comply with rule 606	Date:	09/23/2022
Type	OTHER		
Comment:	Stained soil around well head, PU motor, produced water tank, and crude oil load out line.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	09/23/2022

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas powered motor		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.987011,-104.893998
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment wiht crude oil tank				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203817 Type: WELL API Number: 001-09377 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 12/30/2019 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: Submit reports
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday August 23, 2022 at approximately 11:52AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Zarlengo 24-4 Operator: Providence operating API#: 001-09377 County: Adams While there, I observed a producing well site and production facility During this inspection the following possible compliance issues were observed: Weeds: Rule 606 Corrective action date of 9-23-22 See photos 1,2,5,6 Unused equipment: Rule 606 Corrective action date of 9-23-22 see Photos 1,2 Stained soil: Rule 905 e Corrective action date of 9-23-22 See photos 1,3,8,9 Bird netting: Rule 608 e Corrective action date of 9-2-22 see photo 7 Weather conditions: Clear A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/23/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403144643	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5837882
693507796	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5837881