

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2022

Submitted Date:

08/26/2022

Document Number:

696304395

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 306094 _____ PETRIE, ERICA _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 65110
 Name of Operator: O'BRIEN ENERGY RESOURCES CORP
 Address: 18 CONGRESS ST STE 207
 City: PORTSMOUTH State: NH Zip: 03801
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
 4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joe		joeobenergy@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285560	WELL	TA	07/30/2020	GW	123-23984	LOST CREEK 31	TA

General Comment:

Re-Inspection to FIR 696304205 dated 05.19.2022

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign has been knocked down at Entrance to Lease Road; see photos		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced Water Tank Lables - NFPA, Content and Capacity have STILL faded no longer visible; see photos. Orginal Corrective Action date remains the same		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/20/2022
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Motor Valve at Separator Site STILL REMAINS; see photos. Same Corrective Action Date remains the the same		
Corrective Action:	Comply with Rule 606	Date:	06/20/2022
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Wellhead and at Separator site STILL Remain. (Separator has been removed) (Wellhead Riser covered by weeds) See photos Same Corrective Action Date remains the same		
Corrective Action:	Comply with Rule 606	Date:	05/27/2022
Type	WEEDS		
Comment:	Weeds on Location; see photos		
Corrective Action:	Comply With Rule 606	Date:	09/05/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barbed Wire		

Corrective Action:		Date:	
Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	TA Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.216720,-104.321670
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 285560 Type: WELL API Number: 123-23984 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Seeding				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Re-Inspection. Weeds on Location. Unmarked Risers STILL REMAIN. Unused Motor Valve STILL REMAINS. Water Tank Labels STILL faded.	petrie	08/26/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403148713	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5841158
696304396	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5841143