

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/01/2022

Submitted Date:

09/02/2022

Document Number:

696304414

FIELD INSPECTION FORMLoc ID 433070 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

22 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433059	WELL	PR	08/01/2020	OW	123-37445	Rohn State LD04-65HN	PR
433073	WELL	PR	08/01/2020	OW	123-37455	Rohn State LD03-65HN	PR
433077	WELL	PR	08/01/2020	OW	123-37458	Rohn State LD03-66-1HN	PR
433094	WELL	PR	08/01/2020	OW	123-37470	Rohn State LD04-66-1HN	PR
433107	WELL	PR	08/01/2020	OW	123-37480	Rohn State LD04-67-1HN	PR
433108	WELL	PR	08/01/2020	OW	123-37481	Rohn State LD04-66HN	PR
433110	WELL	PR	08/01/2020	OW	123-37483	Rohn State LD03-66HN	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Labels missing on Chemical Tank at VRTs. If STILL in used replace Labels or remove from Location if not in use (Unused Equipment) See photos		
Corrective Action:	Install sign to comply with Rule 605.h. or Comply with Rule 606 if not in use	Date:	10/03/2022
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked/Faded Markings on 3" Risers with the Flat Top in the South Side of Tank Berm, see photos		
Corrective Action:	Comply with Rule 606	Date:	09/09/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire Fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: VRU	# 2		
Comment:			

Corrective Action:				Date:	
Type: Plunger Lift	# 8				
Comment:					
Corrective Action:				Date:	
Type: Compressor	# 2				
Comment:					
Corrective Action:				Date:	
Type: Emission Control Device	# 9				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 8				
Comment:	Appear to be plumbed to Surface				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 12				
Comment:					
Corrective Action:				Date:	
Type: Other	#				
Comment:	23 Sand Traps				
Corrective Action:				Date:	
Type: LACT	# 1				
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator	# 5				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 20				
Comment:					
Corrective Action:				Date:	
Type: VRT	# 3				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL		OTHER	STEEL AST		40.776630,-103.860710	
Comment:	24 Tanks					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	750 BBLS	

Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type		Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST			40.777520,-103.862110	
Comment:		Maintenance Tank					
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type		Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	BV CONCRETE			,	
Comment:		Drain Vaults					
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity) 60 BBLs							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:		Comment: Shares berm with the Crude Oil Tanks					
Corrective Action:							Date:
Contents	#	Capacity	Type		Tank ID	SE GPS	
PRODUCED WATER	12	500 BBLs	FIBERGLASS AST			40.776830,-103.861050	
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	433059	Type:	WELL	API Number:	123-37445	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433073	Type:	WELL	API Number:	123-37455	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433077	Type:	WELL	API Number:	123-37458	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433094	Type:	WELL	API Number:	123-37470	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433107	Type:	WELL	API Number:	123-37480	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433108	Type:	WELL	API Number:	123-37481	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433110	Type:	WELL	API Number:	123-37483	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment [Weeds in Interim Reclamation Area at Entrance; see photos](#)

Corrective Action [Comply with Rule 606 and 1003.f.](#)

Date **09/19/2022**

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Chemical Tank at VRTs - Labels or removed if not in use. Unmarked 3" Risers in Tank Berm - South Side	petrie	09/01/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403155213	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5847171
696304417	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5847168