

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2022

Submitted Date:

09/07/2022

Document Number:

693507849**FIELD INSPECTION FORM**Loc ID 318991 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242651	WELL	PR	07/01/2017	OW	123-10442	JOSEPHINE B MILES 5	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign faded not legible		
Corrective Action:	Comply with rule 605	Date:	10/07/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	mechanical issue: Well leaking around tubing on well head and 2" flow line appears to be leaking around 2" hammer union.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 09/08/2022
Type	WEEDS		
Comment:	Weeds around electric equipment		
Corrective Action:	Comply with rule 606		Date: 09/14/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Hog wire		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 242651 Type: WELL API Number: 123-10442 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 06/23/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 7

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 7

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday September 7, 2022 at approximately 10:00AM, I, Inspector Randy Silver, Conducted an on-site inspection Due to Directors order to suspend all production on 17 wells.</p> <p>Location: Josephine B Miles #5</p> <p>Operator: KP Kauffman</p> <p>API#: 123-10442</p> <p>County: Weld</p> <p>While there, I observed a shut in well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign: Rule 605 Corrective action date of 10-7-22 See photo 5</p> <p>Weeds: Rule 606 Corrective action date of 9-14-22 See photo 4</p> <p>Mechanical issue: Rule 608 e Corrective action date of 9-8-22 See video and photo 3</p> <p>Spoke with Mani Silva KPK Supervisor at approx... 10:05 AM he stated would send guys to look at active leak around tubing on well head as seen in video and repair 2" flow line that appears to be leaking around hammer union.</p> <p>Weather conditions: Clear</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	09/07/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403158130	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5850048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5850048</a>
693507850	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5850025">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5850025</a>
693507851	Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5850026">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5850026</a>