

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2022

Submitted Date:

09/26/2022

Document Number:

702500483**FIELD INSPECTION FORM**Loc ID 322118 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10506Name of Operator: SEELEY OIL COMPANY LLCAddress: PO BOX 1058City: CORTEZ State: CO Zip: 81321**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Seeley, Nathaniel	(970) 565-2136	nathaniel@seeleyoil.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209013	WELL	SI	02/01/2020	OW	033-06118	SOUTHEAST SPARGO 1	SI

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Open top tank is labeled both produced water and crude oil (IMG 06). Also tank capacity is not labeled.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/26/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	TRASH		
Comment:	Empty water bottles and oily gloves are trash (IMG 07, IMG 08, IMG 09).		
Corrective Action:	Remove trash per rule 606.	Date:	10/05/2022
Type	WEEDS		
Comment:	Weeds at produced water tank (IMG 05).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k	Date:	10/05/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	OTHER		
Comment:	Open top tank is enclosed by wire fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 3		
Comment:	Separator vent stacks are screened.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	No conspicuously posted calibration record, meters must be calibrated if returned to service.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	2 rig anchors not marked properly (IMG 04).		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	10/12/2022
Type: Flow Line	# 15		
Comment:	3 2" lines from wellhead to northern separator, 2" line from northern separator to gas powered prime mover, 2" line from northern separator to produced water, 3" line from northern gas meter run to crude oil tank. 3 2" lines from southern separator to crude oil tank, 2 2" lines from separators to open top tank, 2 2" lines at eastern separator, 2" line from gas meter run compressor station. Lines at wellhead are no longer in use and are locked out tagged out.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1		Open Top		37.578513,-108.997526
Comment:	Open top tank labeled both produced water and crude oil, with no capacity labeled. Open top is covered by steel mesh screen.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		37.578105,-108.997793
Comment:	2 above ground produced water tanks, each with 400 bbl capacity				
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	1000 BBLs	STEEL AST		37.578009,-108.997712	
Comment:	2 above ground crude oil tanks, each with 1000 bbl capacity.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	209013	Type:	WELL	API Number:	033-06118	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Flow lines at wellhead no longer connected (IMG 10)."/>									
Corrective Action: <input type="text"/> Date: _____									



Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Culverts	Pass					
		Gravel	Pass			
Ditches	Pass					
Berms	Pass					
		Compaction	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403178597	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5870567
702500484	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5870563