

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2022

Submitted Date:

09/27/2022

Document Number:

699804971**FIELD INSPECTION FORM**Loc ID 311685 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211492	WELL	PR	08/08/2000	GW	045-07252	GIBSON GULCH UNIT 3-31 B	PR

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 9/27/22 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC GGU RODREICK-66S91W /31NENW. Location #311685 in Garfield County Colorado. While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1) Loadline open ended with a corrective action date of 10/4/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:	All wells on plunger lift				
Corrective Action:				Date:	
Type: Other	# 1				
Comment:	Loadline open ended.				
Corrective Action:	All loadlines will be bullplugged or capped.			Date:	10/04/2022

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211492	Type:	WELL	API Number:	045-07252	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Gravel						
		Compaction				
		Berms				
Sediment Traps						
		Sediment Traps				
		Culverts				
		Check Dams				
Compaction						
Ditches						
		Ditches				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Refer to equipment for corrective actions.	depaoloc	09/27/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403183482	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874726">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874726</a>
699804972	Photos for Insp. #699804971	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874710</a>