

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2022

Submitted Date:

09/30/2022

Document Number:

702500522

**FIELD INSPECTION FORM**

Loc ID 334280 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	<a href="#">All SW field inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216246	WELL	PR	01/09/1992	CBM	067-07852	STATE CD 1	PR
294770	WELL	PR	01/04/2016	GW	067-09499	STATE CD 3	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank sign is deteriorated (IMG 05).		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 11/30/2022
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Landowner appears to be storing dump truck on location (IMG 06). Oil is dripping from truck and impacting surface material. This is a similar comment from inspection doc# 695103007.		
Corrective Action:	Remove unused equipment per rule 603.f		Date: 11/30/2022
Type	OTHER		
Comment:	Lube oil at #3 wellhead (IMG 03). Lube oil at #1 wellhead has impacted surface material (IMG 04).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.		Date: 10/15/2022
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Equipment on this location is enclosed by stock panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:	Separator vent stacks are screened properly.		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment: <a href="#">Gas meters are calibrated within the last year.</a>		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 5	
Comment: <a href="#">Telemetry, electric panel, electric cabinet, 2 pump control panels.</a>		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		Date:
Corrective Action:		Date:
Type: Flow Line	# 6	
Comment: <a href="#">2 3" and 2 2" lines from wellhead to separators, 2 lines from separators to produced water</a>		Date:
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment: <a href="#">Bradenheads are accessible.</a>		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.188027,-107.631075
Comment: <a href="#">Partially buried produced water tank.</a>					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

**Venting:**

Yes/No		Date:
Comment:		Date:
Corrective Action:		Date:

**Flaring:**

Type		Date:
Comment:		Date:
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 216246 Type: WELL API Number: 067-07852 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 294770 Type: WELL API Number: 067-09499 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					
Rip Rap	Pass					
		Gravel	Pass			
		Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403184115	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5875296">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5875296</a>
702500523	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5875291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5875291</a>