

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S94W /21NESE

Location ID: 324180



Photo #8126 From entrance to location.



Photo #8127 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S94W /21NESE

Location ID: 324180



Photo #8128 Multiple loadline open ended.



Photo #8129 Multiple loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S94W /21NESE

Location ID: 324180



Photo #8131 Rill erosion occurring on location.



Photo #8132 Run off of location is not being controlled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH-66S94W /21NESE

Location ID: 324180



Photo #8133 Sediment migrating off location.



Photo #8134 Sediment is choking off vegetation.