

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2022

Submitted Date:

10/19/2022

Document Number:

695106877

**FIELD INSPECTION FORM**

Loc ID 322221 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 44390  
Name of Operator: JAVERNICK OIL  
Address: 3040 E MAIN  
City: CANON CITY State: CO Zip: 81212

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209982	WELL	PR	10/27/2005	OW	043-06060	YELLICO 3-2	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	PHOTO 9: TRASH OR DEBRIS TO THE NORTH OF CRUDE OIL TANK. PHOTO 10: TRASH OR DEBRIS TO THE NORTH OF CRUDE OIL TANK.		
Corrective Action:	REMOVE TRASH AND DEBRIS PER RULE 606.	Date:	11/19/2022
Type	OTHER		
Comment:	PHOTO 5: AREA OF IMPACTED SOIL AROUND WELLHEAD. PHOTO 6: AREA OF IMPACTED SOIL UNDER 3" LOADOUT LINE FROM CRUDE OIL TANK. PHOTO 7: AREA OF IMPACTED SOIL UNDER 3" LOADOUT LINE FROM CRUDE OIL TANK NEAR LOAD OUT CONTAINMENT. PHOTO 8: AREA OF IMPACTED SOIL UNDER 2" LINE ON THE EAST SIDE OF CRUDE OIL TANK.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.	Date:	11/19/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		38.335696,-105.099169
Comment:	PHOTO 12: 2" RISER ON CRUDE OIL TANK IS OPEN TO ATMOSPHERE WITHOUT A PRESSURE CONTROL DEVICE, FLIR VIDIO SHOWS 2" IS VENTING GAS WITHOUT PRESSURE CONTROL.				
Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).				Date: 10/25/2022

**Paint**

Condition Adequate

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	<input type="text"/>			

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	YES		
Comment:	PHOTO 13: VALVE TO TBG/CSG ANNULUS IS OPEN AND FLIR VIDIO SHOWS WELL IS CONTINUOUSLY.		
Corrective Action:	Close well to atmosphere as directed by Rule 434.b.(1).	Date:	<u>10/20/2022</u>

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 209982 Type: WELL API Number: 043-06060 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/22/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403203115	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891372">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891372</a>
695106878	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891361">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891361</a>
695106880	FLIR VIDEO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891362">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891362</a>