

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2022

Submitted Date:

10/31/2022

Document Number:

700901225**FIELD INSPECTION FORM**Loc ID 319819 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 41550Name of Operator: TYLER ROCKIES EXPLORATION LTDAddress: P O BOX 119City: TYLER State: TX Zip: 75710-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Strawn, Mark	930-595-4886	texcomo@sbcglobal.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201475	WELL	SI	12/01/2020	OW	001-06878	UPRR-LINNEBUR 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	• Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment.		
Corrective Action:	Within a designated setback, remove weeds, dead weeds and debris per Rule 606. Corrective Action Date 11/11/2022. See attached photo # 1 through 7.		Date: 11/30/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	Rule 906: Stained soil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 11/30/2022 to remove stained soil. See attached photo # 2 and 4		Date: 11/30/2022
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.747787,104.031001
Comment:	Rule 906: Stained soil.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 11/30/2022 to remove stained soil. See attached photo # 2 and 4				
				Date:	11/30/2022

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
001-06878		

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 201475 Type: WELL API Number: 001-06878 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 11/28/2021 Annual Brhd Completed? _____Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday August 25th, 2022. At approximately 11:25am. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: Tyler Rockies Exploration Location name: UPRR-Linnebur 1 API # 001-06878 Location ID #: 319819 County: Adams While there, I observed a Shut in well. During this inspection the following possible compliance issues were observed: • Rule 906: Stained soil. Control and contain spills/releases and clean up per Rule 906. Corrective Action Date 11/30/2022 to remove stained soil. See attached photo # 2 and 4</p> <p>• Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/11/20022 See attached photo # 1 through 7.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	10/31/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
700901226	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5903495