

Inspection Photos

October 31, 2022

Operator: Argali Exploration Company - #3975

Location ID: 312987

Location Name: SPETTER-68N90W/8SWNW

Inspection Document #: 702800867

Moffat County, CO

SWNW Section 8 T8N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SPETTER-68N90W/8SWNW
Location ID: 312987



Photo 1. Photo taken from the east shows an overview of the Location.



Inspection Photos
Location Name: SPETTER-68N90W/8SWNW
Location ID: 312987



Photo 2. Photo shows a tank with no label and no secondary containment. Tank battery signage is absent. Tank is unused equipment.



Photo 3. Photo shows production equipment. The wellhead sign does not comply with Rule 605.d(2).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800867

Inspection Photos
Location Name: SPETTER-68N90W/8SWNW
Location ID: 312987



Photo 4. Photo shows trash (fence wire) on Location.



Photo 5. Photo shows trash (fence wire) on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800867

Inspection Photos
Location Name: SPETTER-68N90W/8SWNW
Location ID: 312987



Photo 6. Photo shows trash (metal cable) present in the fill slope.



Photo 7. Photo shows trash (metal pipe) present in the fill slope.

Inspection Photos
Location Name: SPETTER-68N90W/8SWNW
Location ID: 312987




Photo 8. Photos show two pit overflow areas at the southwest of the Location. Pits have not been properly reclaimed; recontouring is required. Note natural contour of reference area; hillside gradually slopes down toward intermittent stream. Pits must be reclaimed per 1003 Rules.



Inspection Photos

Location Name: SPETTER-68N90W/8SWNW

Location ID: 312987



Photo 9. Photo shows an overview of the eroding cut slope at the north of the Location. Note, the base of the cut slope is vegetated and stable. Erosion is occurring in largely unvegetated areas.



Photo 10. Photo shows rill erosion on the cut slope at the north of the Location. Erosion is occurring in areas which are largely unvegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800867

Inspection Photos
Location Name: SPETTER-68N90W/8SWNW
Location ID: 312987



Photo 11. Photo shows rill erosion occurring on bare areas of the cut slope. Red circle indicates houndstongue (List B Noxious).



Photo 12. Photo shows Canada thistle (List B Noxious) on the pad surface. Canada thistle was also common on the fill slope.

Inspection Photos
Location Name: SPETTER-68N90W/8SWNW
Location ID: 312987



Photo 13. Photo shows reference areas to the north of the Location are densely vegetated and stabilized with perennial grasses.