

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2022

Submitted Date:

11/02/2022

Document Number:

702800868**FIELD INSPECTION FORM**Loc ID: 313044 Inspector Name: O'Malley, Anna On-Site Inspection: ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 3975

Name of Operator: ARGALI EXPLORATION COMPANY

Address: PO BOX 416

City: RANGELY State: CO Zip: 81648

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jeffrey, Carl		jbrduco@yahoo.com	<a href="#">All Inspections</a>
,		argaliexplorationcompany@g mail.com	<a href="#">General Contact</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223438	WELL	PR	08/01/2021	GW	081-06804	STATE 1-31	RI
313044	LOCATION	AC			-	STATE-69N90W 31SWSW	RI

**General Comment:**

On 10/31/2022, Reclamation Specialist O'Malley conducted a reclamation and stormwater inspection at Argali Exploration Company's STATE-69N90W/31SWSW Location #313044 in Moffat County, Colorado.

The following compliance issues were observed during this inspection:

- Noxious weeds
- Methanol tank secondary containment insufficient
- Unmarked anchor(s)

Refer to the "Location," "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	<p>Previous inspection #689806827 observed signs on location have not been updated to reflect operator change. Inspector required Operator to install sign to comply with Rule 605.</p> <p>It was observed in this inspection that the wellhead sign has been updated with current Operator information. Wellhead sign complies with Rule 605.d. This corrective action has been addressed.</p>		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<p>(970) 629-1906</p> <p>Previous inspection #689806827 observed emergency contact information belongs to previous operator. Inspector required Operator to install sign to comply with Rule 605.</p> <p>It was observed in this inspection that the wellhead sign has been updated with current Operator emergency contact information. This corrective action has been addressed.</p>		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	<p>Canada thistle, a List B Noxious Weed was observed throughout the Location. Weed management required in the 2023 growing season. Ongoing weed management required.</p>		
Corrective Action:	Conduct weed management to prevent further establishment and spread of noxious weeds; ongoing weed management required until location passes final reclamation.	Date:	05/01/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
<p>In Containment: No</p> <p>Comment: <input type="text"/></p> <p><input type="checkbox"/> Multiple Spills and Releases?</p>				

**Equipment:**

			corrective date
Type: Gas Meter Run	#		
Comment:	<p>Previous corrective action(s) regarding gas meter calibration records which have not been addressed remain applicable.</p>		
Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	<p>Previous corrective action(s) regarding bradenhead access which have not been addressed remain applicable.</p>		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1				,
Comment:	<input type="text"/>				

Corrective Action:		Date:	
<b>Paint</b>			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Maintenance
Earth	Inadequate	Walls Insufficient	Inadequate
Comment:	It was observed in this inspection that secondary containment for the methanol tank on Location is insufficient. The earthen berm walls are degraded and are insufficient.		
Corrective Action:	Repair or install berms or other secondary containment devices.		Date: 12/02/2022
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	223438	Type:	WELL	API Number:	081-06804	Status:	PR	Insp. Status:	RI
Facility ID:	313044	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

No waste and/or debris observed.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

No unused equipment observed.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Fail

Comment \_\_\_\_\_

Anchor(s) observed to be unmarked.

Corrective Action \_\_\_\_\_

Install proper guy line markers per Rule 1003.a or remove anchor if equipment is unnecessary.

Date **11/13/2022**

1003b. Area no longer in use? Pass Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation In

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? F

Comment

Refer to the "Location" section of this inspection report for weed control corrective action.

Areas no longer in use/unnecessary for production operations are vegetated with native and introduced perennial grasses (crested wheatgrass, western wheatgrass, prairie jungrass) and native shrubs (sagebrush). Revegetation is in process. Cut and fill slopes are evident; entire Location must be recontoured during final reclamation.

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment

Corrective Action: <input style="width: 90%;" type="text"/>	Date: <input style="width: 90%;" type="text"/>
Overall Final Reclamation <input style="width: 30%;" type="text"/>	Well Release on Active Location <input style="width: 30%;" type="checkbox"/>
	Multi-Well Location <input style="width: 30%;" type="checkbox"/>

  

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

  

Comment:

Corrective Action:

Date:

  

**Pits:**    ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403217234	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5904066">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5904066</a>
702800869	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5904064">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5904064</a>