

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2022

Submitted Date:

11/22/2022

Document Number:

700704717

FIELD INSPECTION FORMLoc ID 313308 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10776

Name of Operator: CROWHEART ENERGY LLC

Address: 1225 17TH STREET SUITE 2950

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|--------------------------------|-----------------|
| Crowheart | | m.grijalva@crowheartenergy.com | |
| Crowheart | | regulatory@crowheartenergy.com | All Inspections |
| Fiddes, Callie | (720) 738-9443 | c.fiddes@crowheartenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 285957 | WELL | TA | 08/01/2021 | GW | 081-07328 | LANDING STRIP FEDERAL 1 | TA |

General Comment:**COGCC Inspection Report Summary**

On Thursday 11/17/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection for P/A operations at Crow heart energy Landing Strip Federal 1, at Location # 313308 in Moffet county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed the start of P/A operations. The rig was setting up. Company man informed that the well had approx. 1200 PSI at the start, blew down and had production water retuning. They were waiting for 9 pound mud to show up to kill well. This location is within or in close proximity to a CPW sensitive Wildlife Habitat, Elk winter concentration, NSO habitat, Wildlife Management and Federal land.

During this inspection the following compliance issues were observed:

1. Random debris and stored equipment.
2. Lack of stabilization on cut slope and erosion

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | OTHER | | |
| Comment: | Entrance | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|-------------------------------------------------------------|-------|------------|
| Type | DEBRIS | | |
| Comment: | Random debris and stored equipment. | | |
| Corrective Action: | Remove all debris and stored equipment. Weather permitting. | Date: | 01/03/2023 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------|----------------------------------------------------------|-------|-----------------|
| | | | corrective date |
| Type: Other | # 1 | | |
| Comment: | Workover rig and associated equipment for P/A operations | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Well head | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 285957 Type: WELL API Number: 081-07328 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: P/A operations are being started

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: 1. Lack of stabilization on cut slope and erosion

Corrective Action: Install or repair required BMPs Weather permitting

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 700704719 | Photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923022 |