

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2022

Submitted Date:

11/13/2022

Document Number:

688313211

FIELD INSPECTION FORM

Loc ID 412995 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96340
Name of Operator: WIEPKING-FULLERTON ENERGY LLC
Address: 106 GLENMOOR LN
City: ENGLEWOOD State: CO Zip: 80113

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Halde, Kerry	(719) 340-0329	haldeoil@hotmail.com	All Inspections
Shalberg, Greg	(719) 688-3547	gregshalberg@aol.com	
MacLaren, Joe		joe.maclaren@state.co.us	Flowline Inspector
Boone, Linda	(720) 271-8605	LDBoonePar@aol.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412994	WELL	PR	04/01/2021	OW	073-06384	ALOHA MULA 2	SI

General Comment:

[Routine Field Inspection](#)
[Gas leak on flowline to battery in pasture was repaired.](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	719-340-0329		Date:
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	Flir survey found flowline gas leak in pasture. Inspector notified Wiepking-Fullerton on 9/29/2022 of finding. GRADE 1 GAS LEAK means a gas leak that ignites or represents an existing or probable hazard to persons or property and requires immediate repair or continuous action until the conditions are no longer hazardous.		
Corrective Action:	Properly report grade 1 gas leaks to comply with Rule 1104.k and/or determine if this was a Grade 1 gas leak after contacting COGCC flowline people. GRADE 1 GAS LEAK means a gas leak that ignites or represents an existing or probable hazard to persons or property and requires immediate repair or continuous action until the conditions are no longer hazardous.		Date: 11/15/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1	corrective date	
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment: electric motor		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 412994 Type: WELL API Number: 073-06384 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI
 403133096 42 (MIRU) -00 Notice Type: MIRU
 Date&Time: 08/12/2022 08:00 APPROVED 8/11/2022 8/11/2022 WIEPKING-FULLERTON ENERGY LLC

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403235983	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5921635
688313387	Wiepking-Fullerton Aloha Mula 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5921611