

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/22/2022

Submitted Date:

11/22/2022

Document Number:

687400962**FIELD INSPECTION FORM**
 Loc ID 319955 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 28780Name of Operator: FAHEY OIL & GASAddress: 93 SOUTH COUNTY ROAD 159City: STRASBURG State: CO Zip: 80136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|--------------------|----------------|
| fahey, dave | 303-622-9495 | diafahey07@aol.com | owner operator |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 201992 | WELL | SI | 05/01/2021 | GW | 001-07396 | BULLARD 2 | SI |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|----------|-------------|
| Comment: | Adequate | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|--------------------------------|-------|------------|
| Type | WEEDS | | |
| Comment: | Dead weeds throughout location | | |
| Corrective Action: | Comply with Rule 606 | Date: | 11/30/2022 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--|-------|------------|
| Type | TANK BATTERY | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Livestock fence | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Fence in disrepair | | |
| Corrective Action: | Comply with the fencing requirements per the 1002a rules | Date: | 12/02/2022 |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------------------|-----|-------|
| Type: Gas Meter Run | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 39.855677,-104.489560 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|----------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 100 BBLS | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|----------|----------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Shares berm with production tank | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Wells Served By Facilities Above**AirsID**

| |
|------------|
| API Number |
| 001-07396 |

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 201992 Type: WELL API Number: 001-07396 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|--|-------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On (Tuesday) (11/21/2022) at approximately (9::42am), I, Inspector (Keith Huck), conducted an on-site inspection at (Bullard#2) (Fahey Oil and Gas), at (Location#319955) in (Adams,County) Colorado.</p> <p>While there, I observed a Production Facility</p> <p>During this inspection the following possible compliance issues were observed: Weeds around location. See attached pictures</p> <p>Comply with Rule 606 Corrective Action Date:11/30/22</p> <p>Fence around wellhead in disrepair. See attached pictures Comply with the fencing requirements per the 1002a rules Corrective action date 12/2/2022</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | huckk | 11/22/2022 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403237464 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923029 |
| 687400963 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923021 |