

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2022

Submitted Date:

11/22/2022

Document Number:

700704717

**FIELD INSPECTION FORM**Loc ID 313308 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10776

Name of Operator: CROWHEART ENERGY LLC

Address: 1225 17TH STREET SUITE 2950

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crowheart		m.grijalva@crowheartenergy.com	
Fiddes, Callie	(720) 738-9443	c.fiddes@crowheartenergy.com	All Inspections
Crowheart		regulatory@crowheartenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285957	WELL	TA	08/01/2021	GW	081-07328	LANDING STRIP FEDERAL 1	TA

**General Comment:****COGCC Inspection Report Summary**

On Thursday 11/17/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection for P/A operations at Crow heart energy Landing Strip Federal 1, at Location # 313308 in Moffet county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed the start of P/A operations. The rig was setting up. Company man informed that the well had approx. 1200 PSI at the start, blew down and had production water retuning. They were waiting for 9 pound mud to show up to kill well. This location is within or in close proximity to a CPW sensitive Wildlife Habitat, Elk winter concentration, NSO habitat, Wildlife Management and Federal land.

During this inspection the following compliance issues were observed:

1. Random debris and stored equipment.
2. Lack of stabilization on cut slope and erosion

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Entrance		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris and stored equipment.		
Corrective Action:	Remove all debris and stored equipment. Weather permitting.	Date:	01/03/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well head		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Workover rig and associated equipment for P/A operations		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285957	Type:	WELL	API Number:	081-07328	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: _____									
Comment: <input type="text" value="P/A operations are being started"/>									
Corrective Action: <input type="text"/> Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. Lack of stabilization on cut slope and erosion

Corrective Action: Install or repair required BMPs Weather permitting

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403237465	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923030">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923030</a>
700704719	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923022">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5923022</a>