

Environmental Inspection

November 22, 2022

Operator: WESTERN OPERATING CO - #95620

Location ID: 312292

API: 075-09212

PIT FACILITY IDs: 256303; Propst B2

Inspection Document #: 690900217

Logan County, CO

NESE Section 27 T11N R53W

Alex Fischer

Environmental Supervisor - Western
Colorado, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 1. Sign at pumping unit.

Inspection Photos

Location Name: Propst B #2

Location ID: 312292



Photo 2. Sign at tank battery.



Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 3. Loadout containment basin found open.



Photo 4. Valve in closed position with handle on valve. Note: evidence of livestock was observed in tank tank battery.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 5. Evidence of livestock.




Photo 6. Tank label and placard. Note: Emergency Contact # illegible from a distance.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 7. Un-marked riser at tank battery.



Photo 8. Burrows compromising secondary containment berm.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 9. Burrows compromising secondary containment berm.



Photo 10. Vertical separator.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 11. Hammer union weeping oil and oil staining on ground.



Photo 12. Vertical separator with apparent material removed on south side of concrete pad.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 13. Vertical separator with apparent material removed on south side of concrete pad.



Photo 14. Surface disturbance south of separator approximately 150+ feet in length by 20 feet in width.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292




Photo 15. Charred fence posts from November 2019 fire (Insp Doc #680305948).



Photo 16. Charred fence posts from November 2019 fire (Insp Doc #680305948).

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 17. Trash/debris (cigarette butt) within well fence enclosure.



Photo 18. Bird nest on pumping unit.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 19. Paraffin and oil build up at stuffing box.

Photo 20. Apparent gas leak at wellhead (see attached video DSCN1733.MOV).

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 21. Trash near pit.



Photo 22. Trash near pit.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 23. Trash/debris inside the pit.



Photo 24. Trash/debris inside the pit.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 25. Signs of stormwater run on into the pit.



Photo 26. Trash/debris inside the pit along with stormwater run on into the pit.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 27. South side of pit looking west.



Photo 28. East side of pit looking south. Signs of run on into the pit with inadequate BMPs.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 29. East side of pit looking south. Signs of run on into the pit with inadequate BMPs.



Photo 30. Erosion along the north side of the pit.

Inspection Photos
Location Name: Propst B #2
Location ID: 312292



Photo 31. Stressed vegetation in center of photo.



Photo 32. Stressed vegetation.