

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2022

Submitted Date:

12/05/2022

Document Number:

697601948

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Ahmadian, Alexander On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Meis, Craig		cmeis@kpk.com	<a href="#">KPK Environmental</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
LLC, Marcom	208-201-8280	PrimaryContractor@marcomllc.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481725	SPILL OR RELEASE	CL	07/13/2022		-	Milton Nelson	EI

**General Comment:**

This is an environmental inspection of Spill ID 481725. Any corrective actions from previous inspections that have not been addressed are still applicable.

No operator on environmental personnel were onsite at the time of the inspection.

Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>					
Type	OTHER				
Comment:	Fencing is adequate around the excavation.				
Corrective Action:				Date:	

**Venting:**

Yes/No				
Comment:				
Corrective Action:			Date:	

**Flaring:**

Type				
Comment:				
Corrective Action:			Date:	

**Inspected Facilities**

Facility ID: 481725 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: Groundwater was observed within the excavation in contact with soil impacts and flowline.

Corrective Action: In accordance with 913.d.(1), Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Date: 12/12/2022

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403248936	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932490">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932490</a>
697601949	Photo Documentation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932489">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5932489</a>