

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2022

Submitted Date:

12/19/2022

Document Number:

707900351**FIELD INSPECTION FORM**Loc ID 322216 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209905	WELL	SI	08/01/2022	OW	043-05180	J J 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	No well head sign but does have battery sign		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around TNK BTRY and equipment		
Corrective Action:	Comply with rule 606	Date:	11/12/2022
Type	OTHER		
Comment:	Gauge hatch open or not sealed.		
Corrective Action:	Close and seal gauge hatches when not accessing tank per Rule 608.a.(9).	Date:	12/20/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Guy line anchors not Properly marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 01/02/2023
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible		

Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	11/12/2022
--------------------	---	-------	------------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:	Equipment in geologic hazard area not anchored or inadequately anchored					
Corrective Action:	Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607					Date: 11/12/2022

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 209905 Type: WELL API Number: 043-05180 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/21/2022

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: No evidence of braden head plumbed to surface complete corrective action , complete test and submit correct reports.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday December 19, 2022 at approximately 9:18AM, I, Inspector Randy Silver, conducted an on-site re-inspection per Doc# 695106862. This is a follow up inspection at time of inspection it does not appear any corrective actions have been addressed.</p> <p>Location:JJ #1</p> <p>Operator: Javernick Oil</p> <p>API#:043-05180</p> <p>County: Freemont</p> <p>While there, I observed a shut in well and Tank Battery</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Braden head: Rule 419 a (1) (2) Corrective action date of 11-12-22</p> <p>Tank anchor: Rule 607 Corrective action date of 11-12-22</p> <p>Gauge hatch: Rule 608 a (9) Corrective action date of 12-23-22</p> <p>Guy line anchors: Rule 1003 Corrective action date of 12-23-22</p> <p>Weeds/debris: Rule 606 Corrective action date of 11-12-22</p> <p>Weather conditions: Clear</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	12/19/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900352	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5951554