

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2022

Submitted Date:

12/05/2022

Document Number:

694100026

FIELD INSPECTION FORM

Loc ID 331069 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS
,		cogccinspection@pdce.com	ALL INSPECTIONS

General Comment:

This is an environmental inspection for PDC SEELE-64N67W 31NWN Location ID: 331069. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:				
Type	Area	Volume		
Comment:	<input type="text" value="Barbed wire fence is damaged. Needs to be repaired."/>			
Corrective Action:	<input type="text" value="Comply with the fencing requirements per the 1002a rules"/>		Date:	<input type="text" value="12/23/2022"/>
Type				
Comment:	<input type="text" value="Cattle guards around various equipment is good. However the barbed wire fencing around separator housing is loose and falling down"/>			
Corrective Action:	<input type="text" value="Barbed wire fencing needs to be fixed or replaced."/>		Date:	<input type="text" value="12/05/2022"/>

Venting:				
Yes/No	Area	Volume		
Comment:				
Corrective Action:			Date:	

Flaring:				
Type	Area	Volume		
Comment:				
Corrective Action:			Date:	

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____
Comment:
Corrective Action: Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment:
Corrective Action: Date: _____

Emission Control Burner (ECB): _____
Comment:
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater bmps seem to be adequate at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403264811	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5951000
694100046	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950993