



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Production reports have not been filed with the COGCC since 7/1/21		
Corrective Action:	Submit reports as per Rule 206.	Date:	01/12/2023
Type	WEEDS		
Comment:	weeds unmanaged on location		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	01/12/2023
Type	OTHER		
Comment:	Annual bradenhead test is not current. Contact COGCC engineering. Bradenhead does not appear to be plumbed to surface.		
Corrective Action:	Comply with COGCC annual bradenhead testing rules	Date:	12/22/2022

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	White angle iron around separator, and gas meter run		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	not in use		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment: <b>gas motor, not in use</b>		Date:
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: <b>automation</b>		
Corrective Action:		Date:
Type: Bradenhead	#	
Comment: <b>Does not appear to be plumbed to surface</b>		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 202599 Type: WELL API Number: 001-08004 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: No bradenhead test on file

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: \_\_\_\_\_      Pit ID: \_\_\_\_\_      Lat: \_\_\_\_\_      Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: Metal Grid      Netting Condition: Good

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 12/12/22 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Antelope Farms 1-24 Company Name- API- 05-001-08004 In Adams County Colorado. While there, I observed SI well During this inspection the following possible compliance issues were observed: Annual bradenhead test is not current. Contact COGCC engineering. Bradenhead does not appear to be plumbed to surface. Comply with COGCC annual bradenhead testing rules 12/22/22 weeds unmanaged on location Comply with COGCC housekeeping rules 1/12/23 Production reports have not been filed with the COGCC since 7/1/21 Submit reports as per Rue 206 1/12/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	12/12/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403264698	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950851">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950851</a>
699504338	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950844">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5950844</a>