

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2023

Submitted Date:

02/06/2023

Document Number:

702200044**FIELD INSPECTION FORM**Loc ID 321344 Inspector Name: HICKEY, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 79905

Name of Operator: SMITH OIL PROPERTIES INC

Address: PO BOX 219

City: BYERS State: CO Zip: 80103

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

General Comment:

OWP Inspection in response to Email from Boulder County.

COGCC Comments

Comment	User	Date
Dried liquid residue observed on master valve and other pieces of plumbing and equipment. No liquid discharge was observed. No E&P waste was observed on the ground. No sheen was observed on the precip in the area. Minor gas discharge at the packing rubbers shown with soap bubbles in attached photos. None detected with 4 gas meter.	hickeymi	02/06/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702200045	Video of bubble formation on the Futhy-Karma 1-26	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014121
702200047	More soap	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014124