

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2023

Submitted Date:

03/01/2023

Document Number:

709700014

**FIELD INSPECTION FORM**Loc ID 320468 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10547

Name of Operator: HELENA RESOURCES INC

Address: 2960 SIMMS DR

City: LAKEWOOD State: CO Zip: 80215

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pagano, Theodore	(970) 590-3944	tapagano@helena-resources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256027	WELL	PR	06/30/2008	GW	001-09396	GASPAR 11-1	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil near gate into production tanks. See attached pictures		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	03/31/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Chain Link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chain Link		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain Link		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	Appears to be plumbed to surface	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.999329,-104.957078
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		,
Comment:	Netting on open top tanks inadequate. See attached pictures				
Corrective Action:	Comply with rule 608.a.(13)				Date: 03/08/2023

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Shares berm with production tank		
Corrective Action:		Date:	
<b><u>Wells Served By Facilities Above</u></b>			
<b><u>AirsID</u></b>			
API Number	API Number	AirsID	
001-09396			
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 256027 Type: WELL API Number: 001-09396 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On (Tuesday, February 28th) at approximately (11:27am). I, Inspector Keith Huck, conducted an on-site inspection.</p> <p>Operator: Helena Resources</p> <p>Location name: Gasper 11-1</p> <p>API # 001-09396</p> <p>Location ID #: 320468</p> <p>County: Adams</p> <p>While there, I observed a (Production) well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil near gate into production tanks. See attached pictures</p> <p>Control and contain spills/releases and clean up per Rule 912.a.</p> <p>Corrective Action Date: 3/31/2023</p> <p>Netting on open top tanks inadequate. See attached pictures</p> <p>Comply with rule 608.a.(13)</p> <p>Corrective Action Date: 3/08/2023</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	huckk	03/01/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403334027	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6036734">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6036734</a>
709700015	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6036732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6036732</a>