

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2023

Submitted Date:

03/06/2023

Document Number:

702801311

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐

334610 O'Malley, Anna 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270995	WELL	PR	01/07/2004	GW	045-09809	BASS 14-10A (G14W)	RI
271010	WELL	PR	12/08/2004	GW	045-09822	BASS 14-6D (G14W)	RI
271011	WELL	PR	07/01/2019	GW	045-09823	BASS 14-14A (G14W)	RI
271012	WELL	PR	12/24/2004	GW	045-09824	BASS 14-7B (G14W)	RI
271013	WELL	PR	10/01/2021	GW	045-09825	BASS 14-2D(G14W)	RI
271014	WELL	PR	12/15/2004	GW	045-09826	BASS 14-11B(G14W)	RI
334610	LOCATION	AC			-	BASS-67S93W 14SWNE	RI

General Comment:

On 3/3/2023, Reclamation Specialist O'Malley conducted a reclamation inspection at Caerus Piceance LLC's BASS-67S93W/14SWNE Location #334610 in Garfield County, Colorado.

This is a follow up to inspection document #702801267 to document compliance with corrective actions.

The following compliance issues were observed during this inspection:
- Staining/leaking at produced water/condensate tank drain

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	<p>Previous inspection #702801267 observed staining below produced water/condensate tank drain line within tank battery secondary containment. Inspector required Operator to clean up and properly dispose of stained material. Operator submitted FIR Resolution #403326590 indicating the corrective action was addressed.</p> <p>It was observed in this inspection that fluid is leaking from the produced water/condensate tank (#81309) drain. Although previously observed staining was removed, new/additional staining is present. Operator shall implement measures to ensure fluid does not continually leak from tank drains.</p>			
Corrective Action:	Clean up and properly dispose of stained material. Fix drain to prevent leaks.			Date: 03/21/2023

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	Wildlife protection BMPs (caps) have been installed on black corrugated piping at the tank battery. Corrective action form inspection #702801267 has been addressed.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Bull plug installed on tank # 81308. Corrective action form inspection #702801267 has been addressed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: <u>270995</u>	Type: <u>WELL</u>	API Number: <u>045-09809</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271010</u>	Type: <u>WELL</u>	API Number: <u>045-09822</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271011</u>	Type: <u>WELL</u>	API Number: <u>045-09823</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271012</u>	Type: <u>WELL</u>	API Number: <u>045-09824</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271013</u>	Type: <u>WELL</u>	API Number: <u>045-09825</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>271014</u>	Type: <u>WELL</u>	API Number: <u>045-09826</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>334610</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403338422	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6041892
702801312	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6041884