

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2023

Submitted Date:

03/13/2023

Document Number:

708300178

FIELD INSPECTION FORMLoc ID 432260 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432258	WELL	PR	06/30/2021	GW	045-21934	Homer Deep Unit 9-41BH	PR
432261	WELL	PR	03/01/2018	GW	045-21935	Homer Deep Unit 9-41AH	PR
438407	WELL	PR	03/03/2015	GW	045-22488	Homer Deep Unit 9-41CH	PR

General Comment:**COGCC Inspection Report Summary**

On 3/13/2023 at approximately 11:40, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, Homer Deep Unit/9-41 at Location ID #432260 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Weeds across location
- 2) Open-ended load lines at produced water tanks
- 3) Gas meter calibration record not conspicuously posted

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds on location		
Corrective Action:	Comply with Rule 606	Date:	03/20/2023
Type	OTHER		
Comment:	Open-ended load lines on both produced water tanks		
Corrective Action:	Cap/plug load lines	Date:	03/28/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Livestock paneling		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 3		corrective date
Comment:	Gas meter calibration record not conspicuously posted		

Corrective Action:	Display legible meter calibration record in conspicuous location		Date:	03/23/2023
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Chemical tank with containment			
Corrective Action:			Date:	
Type: Bradenhead	# 3			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 3			
Comment:	All wells on plunger lift			
Corrective Action:			Date:	
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	HEATED STEEL AST		,	
Comment:	Reference Housekeeping section for corrective action					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 432258 Type: WELL API Number: 045-21934 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 432261 Type: WELL API Number: 045-21935 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 438407 Type: WELL API Number: 045-22488 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Gravel						
		Ditches				
Compaction						
		Culverts				
Tracking Pad						
Retention Ponds						
Ditches						
Check Dams						
Berms						
				Material Handling And Spill Prevention		
		Gravel				
		Berms				
Culverts						
Rip Rap						
		Tracking Pad				

Comment: Location lacks stabilization which could lead to future vehicle tracking issues

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403344979	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6048996
708300179	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6048993