

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/23/2023

Submitted Date:

03/24/2023

Document Number:

707800241

**FIELD INSPECTION FORM**

Loc ID 335040	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>Findings:</b> 19 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299214	WELL	PR	03/27/2010	GW	045-17614	MILLER 33B-36-692	PR
299215	WELL	PR	03/27/2010	GW	045-17615	MILLER 33C-36-692	PR
299216	WELL	PR	04/13/2010	GW	045-17616	MILLER 44D-36-692	PR
299217	WELL	PR	04/13/2010	GW	045-17617	MILLER 43A-36-692	PR
299218	WELL	PR	04/28/2010	GW	045-17618	MILLER 43D-36-692	PR
299219	WELL	PR	04/28/2010	GW	045-17619	MILLER 43C-36-692	PR
299220	WELL	PR	04/28/2010	GW	045-17620	MILLER 33D-36-692	PR
299221	WELL	PR	04/26/2010	GW	045-17621	MILLER 42A-36-692	PR
299222	WELL	PR	03/27/2010	GW	045-17622	MILLER 43B-36-692	PR
299223	WELL	PR	04/26/2010	GW	045-17623	MILLER 32A-36-692	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Thursday 3/23/2023, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Miller 33B, at Location # 335040 in Garfield county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following compliance issues were observed:

1. Meter calibration card not conspicuously posted.
2. Stored equipment unused hoses and chemical tank.
3. Some access road and areas of location lack stabilization/compaction.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label lacking info		
Corrective Action:	Provide proper labeling	Date:	04/07/2023
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored equipment unused hoses and chemical tank.		
Corrective Action:	Remove stored equipment	Date:	04/28/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments. 1 chem tank is unused/stored see stored equipment for C/A.		
Corrective Action:			Date:
Type: Gas Meter Run	# 10		
Comment:	Meter calibration card not conspicuously posted.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration.		Date: 04/07/2023
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	8	OTHER	HEATED STEEL AST		,	
Comment:	3 tanks are not heated					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLS	
Other (Type)		

**Berms**

Inspector Name: Ramsey, Scott

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	299214	Type:	WELL	API Number:	045-17614	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	299215	Type:	WELL	API Number:	045-17615	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	299216	Type:	WELL	API Number:	045-17616	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	299217	Type:	WELL	API Number:	045-17617	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	299218	Type:	WELL	API Number:	045-17618	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	299219	Type:	WELL	API Number:	045-17619	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	299220	Type:	WELL	API Number:	045-17620	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	299221	Type:	WELL	API Number:	045-17621	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
Ditches						
Culverts						
Compaction	Fail					
		Culverts				
		Compaction	Fail			

Comment: 1. Some access road and areas of location lack stabilization/compaction.

Corrective Action: Install or repair BMP's

Date: 04/28/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403356069	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062242">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062242</a>
707800245	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6062238</a>