

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2023

Submitted Date:

03/28/2023

Document Number:

691201683

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Meis, Craig		cmeis@kpk.com	KPK Environmental
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

General Comment:

COGCC environmental inspection to determine progress on Spill ID 481413/Remediation 22658. This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Incident information:

Spill Discovery Date: 12/27/2021

Days open: 449 days

Last report: 12/1/2022, Operator is out of compliance with approved quarterly reporting schedule and rule Rule 913.e.(3), the next quarterly report was due 8/9/2022

Current site status: Excavation open and fenced with orange construction fencing. E&P waste is stockpiled on location with evidence of previous overtopping. Stormwater controls and fencing have degraded into wind blown debris.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: None present

Corrective Action:

Date: _____

Good Housekeeping:

Type DEBRIS

Comment: Stormwater controls and fencing have degraded into wind blown debris.Corrective Action: Comply with Rule 606.Date: 04/04/2023Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type OTHER

Comment: Orange construction fencing has not been maintained and has become wind blow trash.Corrective Action: Maintain fencing and clean up trash in compliance with Rule 606.Date: 04/04/2023**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment	Stormwater controls around stockpile have not been maintained.			
Corrective Action	Install or repair required BMPs per Rule 1002.f.(2)C			Date: 04/04/2023

Spill/Remediation:

Comment:	Last report on this incident was 12/1/2023.			
Corrective Action:	Operator is out of compliance with approved quarterly reporting schedule and rule Rule 913.e.(3), the next quarterly report was due 3/1/2023			Date: 03/01/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403358840	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6064695
691201684	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6064677