

# Inspection Photos

4/17/2023

Operator: CAERUS PICEANCE LLC #10456

Location #334342

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334342



**Photo 1:** Photos 1-2 taken from the Location entrance. Photos provide an overview of the Location from west, northwest, northeast to east. Photos also examples showing BMPs to stabilize, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient; pad lacks stabilization. Tracking controls not observed.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334342



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334342



April 17, 2023



April 17, 2023

**Photo 3:** Pad lacks stabilization. Stormwater and erosion controls missing or insufficient.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334342



**Photo 4:** Outlet on north end of the Location.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334342



**Photo 5:** Tank battery signage. Photo also show signs or labels at tanks not posted or information too small to read at distance or installed in place where not visible.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334342



**Photo 4:** Signs or labels at tanks not posted or information too small to read at distance or installed in place where not visible. Most of the required labeling information posted towards center of the battery, and not visible from beyond the facility.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334342



**Photo 7:** Plug removed from tank. Small leak appears evident. Plug requires replacement and impacted materials removed.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334342



**Photo 8:** Wind indicator safety equipment not in proper functioning condition.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #334342



**Photo 9:** Photo examples of the interim areas of the Location. Perennial vegetation evident, however vegetation observed predominantly undesirable plant species such as cheatgrass.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334342



**Photo 10:** Reference area vegetation.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334342



**Photo 11:** Photos examples showing stormwater and erosion control BMPs along access road are missing or insufficient. 6 foot measuring stick for reference.