

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2023

Submitted Date:

04/19/2023

Document Number:

702801473

FIELD INSPECTION FORMLoc ID 334637 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211405	WELL	PR	10/01/1999	GW	045-07165	SAVAGE 1-13	RI
270054	WELL	PR	10/27/2005	GW	045-09443	SAVAGE 1-6B (RBI)	RI
270056	WELL	PR	12/14/2004	GW	045-09444	SAVAGE 1-7A (RB1)	RI
334637	LOCATION	AC			-	SAVAGE-67S94W 1NWNE	RI

General Comment:

On 4/17/2023, Reclamation Specialist O'Malley conducted an interim reclamation and stormwater inspection at Caerus Piceance LLC's SAVAGE-67S94W/1NWNE Location #334637 in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Wildlife protection BMPs on stock tank in disrepair
- Bull plug not installed on tank drain

Refer to the "Location," "Reclamation" and Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been addressed.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	Bull plug not installed on tank drain.		
Corrective Action:	Install bull plug.		Date: 04/24/2023
Type: Other	#		
Comment:	Wildlife protection BMP (wire mesh) covering the methanol tank secondary containment stock tank is in disrepair. There are holes in the mesh. Violation of the 900 series rules.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 04/24/2023

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>211405</u>	Type: <u>WELL</u>	API Number: <u>045-07165</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>270054</u>	Type: <u>WELL</u>	API Number: <u>045-09443</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>270056</u>	Type: <u>WELL</u>	API Number: <u>045-09444</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>334637</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment No anchors or anchor markers observed.

Corrective Action _____

Date _____

1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured <u>Pass</u> 80% Revegetation <u>In</u>
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? <u>P</u>	
Comment	Areas of the location not needed for production have been reduced and reclaimed. Interim areas appear vegetated with introduced (smooth brome, crested wheatgrass) and native (bluebunch wheatgrass) perennial grasses as well as introduced forbs (yellow sweetclover). Native shrubs are also present. No noxious weed concerns at the time of this inspection. Full vegetation assessment and definitive species identification was not possible due to dormant season. A follow up inspection will be conducted during a future growing season to determine compliance with 1003 requirements.
Corrective Action	
Date _____	
Overall Interim Reclamation <u>In Process</u>	
<u>Final Reclamation/ Abandoned Location:</u>	
Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____	
Final Land Use: _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____	
Compaction alleviation _____ Dust and erosion control _____	
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____	
Weeds present _____ Subsidence _____	
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	

Comment:						Date _____
Corrective Action:						
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds						
Gravel						
Seeding						
Berms		Gravel				
Compaction		Culverts				
Ditches		Compaction				

Comment:	At the time of this inspection, stormwater and sediment control BMPs have been installed and appear to be in proper functioning condition. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.					Date: _____
Corrective Action:						

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403378430	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6087561
702801474	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6087556