

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2023

Submitted Date:

04/24/2023

Document Number:

690204122

**FIELD INSPECTION FORM**Loc ID 333710 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Maralex		maralextech@gmail.com	
O'HARE A.M.		amo@maralexinc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265538	WELL	PR	10/15/2003	CBM	067-08770	JENNIE ROSE 33-7-3 1	RI

**General Comment:**

On 4/18/2023, Ryan Costa conducted a Location and Stormwater Management inspection.  
See attached photos and additional details within this report

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	No labeling on container. Previous CA not completed.		
Corrective Action:	Install sign or label to comply with Rule 605.h.	Date:	11/26/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	There is a pile of weed debris at the location that needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	05/05/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
	WELLHEAD			
Comment:	Impacted soil previously observed at the wellhead have not been cleaned up. Previous CA not completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 11/03/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	The gate at the location has fallen off the hinges and needs to be repaired.		
Corrective Action:	Comply with 608e. and 1002a Fencing requirements.	Date:	05/05/2023

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is vehicle rutting and track at the location that needs to be repaired and stabilized

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/26/2023

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403381891	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6091418">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6091418</a>
690204123	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6091408">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6091408</a>