

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2023

Submitted Date:

04/24/2023

Document Number:

696304810

FIELD INSPECTION FORMLoc ID 332372 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272211	WELL	SI	11/01/2021	OW	123-22211	FEDERAL PAINT 9-26	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Unused Heater Treater and Concrete blocks.		
Corrective Action:	90 days to remove all Equipment after Plug and Abandon. Well appears to have been Plugged and Abandoned on 10.17.2022 per Form 42 403197697		Date: 05/26/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed Surface		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	TA Wellhead - Well appears to have been Plugged and Abandoned - Not yet Cut and Capped		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 272211 Type: WELL API Number: 123-22211 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA Wellhead - Well appears to have been Plugged and Abandoned per Form 42 403197697 dated 10.14.2022 for a Plug Date of 10.17.2022 - Not yet Cut and Capped
Form 6S - 403319703 dated 02.23.2023 NOT Approved
Form 27 - 403103826 dated 11.09.2022 Approved for Decommission of Facility.

No Form 27 on File for Cut and Cap

No Seeding has begun on Final Reclamation

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspectin. Heater Treater and Concrete Blocks STILL on Location. 90 days to remove all Equipment after Plug and Abandon. Well appears to have been Plugged and Abandoned. TA Wellhead - Well appears to have been Plugged and Abandoned per Form 42 403197697 dated 10.14.2022 for a Plug Date of 10.17.2022 - Not yet Cut and Capped Form 6S - 403319703 dated 02.23.2023 NOT Approved Form 27 - 403103826 dated 11.09.2022 Approved for Decommission of Facility. No Form 27 on File for Cut and Cap No Seeding has begun on Final Reclamation	petrie	04/24/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403382610	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6091827
696304811	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6091817