

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2023

Submitted Date:

05/12/2023

Document Number:

707800360

**FIELD INSPECTION FORM**Loc ID 324674 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 34162

Name of Operator: GILS HOT OIL SERVICE

Address: P O BOX 418

City: STRASBURG State: CO Zip: 80136

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
paine, gilbert	303-622-9751	cherokeeequipment@hotmail.com	owner operator
, COGCC		dnr_cogccengineering@state.co.us	engineering

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212388	WELL	PR	05/01/2021	OW	057-06281	STATE 12-2	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 5/10/2023, I, Inspector Scott Ramsey, conducted a routine inspection at Gils hot oil service State 12-2, at Location # 324674 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well pump jack not operating at time of inspection. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

During this inspection the following compliance issues were observed:

1. No BMP's installed to prevent sediment migration from occurring on location.
  2. Location and access is covered with vegetation.
  3. Lease road shows signs of lack of stabilization/compaction.
  4. Access road to well is not marked or maintained
  5. No API posted on well head
  6. Lack of tank battery signage
  7. Secondary containment is insufficient.
  8. No evidence of Braden Head access.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Lack of Battery signage		
Corrective Action:	Provide proper signage as per the rule	Date:	06/23/2023
Type	WELLHEAD		
Comment:	well head signage is lacking information		
Corrective Action:	Provide proper signage as per the rule	Date:	06/23/2023

**Emergency Contact Number:**

Comment: 911/303-709-0148

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	05/19/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Slick rods and barbed wire		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 0		corrective date
Comment:	No evidence of Braden Head access.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection	Date:	05/22/2023
Type: Other	# 1		
Comment:	Oil well head		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate			Inadequate	
Comment:		Secondary containment is insufficient.			
Corrective Action:		Repair or install berms or other secondary containment devices			
		Date: 06/23/2023			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 212388	Type: WELL	API Number: 057-06281	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing according to data base, valves open.			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1.No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.  
 2. Location and access is covered with vegetation.  
 3. Lease road shows signs of lack of stabilization/compaction.  
 4. Access road to well is not marked or maintained

Corrective Action: **Install, maintain or repair required BMPs**

Date: 06/23/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800366	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113819</a>