

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2023

Submitted Date:

05/15/2023

Document Number:

712700155

**FIELD INSPECTION FORM**

Loc ID 312009 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10766  
Name of Operator: ARKOMA OPERATIONS LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		SJBcompliance@arkomaops.com	<a href="#">All SW Inspections</a>
Price, Andrew	(918) 260-8324	aprice@arkomaops.com	<a href="#">All SW Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281477	WELL	PR	05/29/2020	CBM	067-09089	IGE 108	PR
297341	WELL	PR	10/10/2014	CBM	067-09609	IGE 134	PR

**General Comment:**

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	And wellhead, cattle panel.		
Corrective Action:		Date:	

**Equipment:**

Type		#		corrective date
Prime Mover		2		
Comment:	gas motor			
Corrective Action:				Date:
Bird Protectors		2		
Comment:				
Corrective Action:				Date:
Deadman # & Marked		2		
Comment:				
Corrective Action:				Date:
Flow Line		2		
Comment:	2-3" from wellhead to separator.			
Corrective Action:				Date:
Ancillary equipment		2		
Comment:	Wellhead			
Corrective Action:				Date:
Gathering Line		1		

Comment:	Partially buried valve can.	Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	2-3" from separator to meterhouse. Calibrated wthin 1 year.	Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		37.114490,-107.689900
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment:	Plastic "Polystar" with plastic liner.			
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
067-09609		

**Venting:**

Yes/No	NO	Date:	
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		Date:	
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 281477 Type: WELL API Number: 067-09089 Status: PR Insp. Status: PR

Facility ID: 297341 Type: WELL API Number: 067-09609 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 10/26/2022 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 75 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Berms	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			

Comment: [No visible erosion or sediment migration observed during inspection. Installed wattles need maintenance or removal. See Photo #2.](#)

Corrective Action: [Repair or remove required BMPs per Rule 1002.f.\(2\)C.](#)

Date: 05/31/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403403866	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115095</a>
712700161	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115084</a>