

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2023

Submitted Date:

05/23/2023

Document Number:

700300576

**FIELD INSPECTION FORM**Loc ID 325293 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES LLC

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Williford, Hearne		hwilli@swbell.net	All SW field inspections
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214498	WELL	PR	06/01/2019	OW	067-06101	LONG & SCHLUTER 6	PR

**General Comment:**

Variance ORDER NO. 1-265, The Commission granted permission for operator to produce and combust casing gas only until Jan 15, 2023.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

## Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	OTHER		
Comment:	impacted material below gas motor/fly wheel		
Corrective Action:	clean up and dispose in approved manner per Rules 1002.f and 906	Date:	06/22/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bradenhead	#		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	#		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	#		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		37.120947,-108.086903
Comment:	corroison showing on tank, paint deteriated				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 08/23/2023

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Inadequate
Comment:	Berms have cheat grass and sage brush growing, deep roots of vegetation can compromise impermeability of containment			
Corrective Action:	Maintain containment by removing sage and other vegetation that can have deep roots per Rule 603, 912 and 605.a(4) old rules			Date: 06/23/2023

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: \_\_\_\_\_ Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: \_\_\_\_\_ Temperature: (F) \_\_\_\_\_

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Wellhead(s)
				Oil Tank(s)
				Other
				Flowline

Comment: Gas leak observed on supply line to natural gas motorCorrective Action: Repair leak per Rule 608.eDate: 05/29/2023**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403410563	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123022">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123022</a>
700300582	FLIR video gas leak supply line for motor	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123015">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123015</a>
700300583	impacted material below motor and flywheel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123016">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123016</a>
700300585	stormwater erosion on access road	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123017">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123017</a>
700300586	rutting and erosion on lease road	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123018">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123018</a>
700300587	paint corrosion on tank/sage growing in berms	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123019">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6123019</a>