

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2023

Submitted Date:

06/06/2023

Document Number:

700300607

**FIELD INSPECTION FORM**Loc ID 325521 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 40547

Name of Operator: HOLCOMB OIL &amp; GAS INC

Address: P O BOX 2058

City: FARMINGTON State: NM Zip: 87499

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Holcomb, Jeff	(505) 330-2473	wjholcomb@qwestoffice.net	Owner
, Engineering		dnr_cogccengineering@state.co.us	
,		holcomb.oilgas@gmail.com	All Inspections as of 7/8/2021

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214938	WELL	SI	09/01/2014	GW	067-06543	CASE 1-10	PR

**General Comment:**

On 6/5 and 6/6 Compliance supervisor Steve Labowskie insepcted site and found well producing, separation equipment running and gas venting to an open top tank (presumably from well/open plunger lift). Gas meter was not running and there was no calibration record present. 24 hour operator contact number is invalid. Operator contacted at number given to COGCC by former employee.

Well has been reported as shut in, no monthly Form 7 reporting since 2017. Well was due for MIT 2//5/23. No Form 42 notice for return to production.

Operator was also told verbally on phoine at 13:45 6/6/23 that they must immediately stop ventring and electronically otify COGCC if well has been returned to service. Update monthly Form 7 reporting and meter gas and calibrate meter. Conduct and submit annual bradenhead test and contact COGCC enginnering about 5 year MIT which was due no later than 2/5/2023 and install a valid 24 hour operator contact #

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	only contents and capacity labels		
Corrective Action:	install NFPA label per Rule 605	Date:	07/06/2023
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Number on well sign "505-609-7230" is invalid		
Corrective Action:	Install valid 24-hour operator contact number per Rule 605	Date:	06/08/2023

**Good Housekeeping:**

Type	WEEDS		
Comment:	noxious weeds and undesirable plant species observed (see photos)		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:	meter not running, no meter calibration record visible		
Corrective Action:	meter gas and display calibration record from within last year per Rules 430.d (1&2)	Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
		Date:		

**Venting:**

Yes/No	YES		
Comment:	Gas observed continuously venting to atmosphere at open top tank with FLIR camera. Gas also heard bubbling.		
Corrective Action:	Immediately stop venting gas to atmosphere per Rule 903.d	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 214938 Type: WELL API Number: 067-06543 Status: SI Insp. Status: PR**Producing Well**Comment: Well appears to be producing, separation equipment is runnoin (see video attachment), plunger is venting to open top tank. Meter is not runnoin. No monthly Form 7s since 2017.Corrective Action: Retroactively submit nitiuce of return to service per Rule 405.p if well was returned to service.Date: 06/06/2023Submit monthly Form 7s per Rule 413**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well reported as shut in, no monthly Form 7 reports since 2017. No notice of return to production. No 5 year MITCorrective Action: Perform 5 MITDate: 07/06/2023**BradenHead**Date of Last Brhd Test: 01/25/2018 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

06/06/2023Corrective Action: Complete annual bradenhead test and submit Form 17 per Rule 419.c

Date: \_\_\_\_\_

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Calm Speed: 1-3 (mph) Direction From: NW Weather: Partly Temperature: (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
-------------------	-------	-----------------	-------

Equipment
Wellhead(s)
Separation Equipment
Water Tank(s)

Comment: see "venring" section for corrective action at open top tank/plunger liftCorrective  
Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403424974	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137520">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137520</a>
700300608	FLIR open top tank/plunger lift venting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137504">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137504</a>
700300609	FLIR open top still venting 8 min later	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137505</a>
700300611	well sign adn iunvalid operator contact #	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137506</a>
700300612	video and audio of production equipment operating	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137507">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137507</a>
700300613	open top tank, no NFPA placard	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137508</a>