

Final Reclamation Inspection

July 12, 2023

Operator: GADECO LLC - 10673

Location ID: 331970

Inspection Document #: 697504769

Weld County, CO

NWNW Section 26 T9N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Croissant #4
Location ID: 331970



Photo 1. ECMC GISOnline aerial imagery from 2019. Photo illustrates the approximate surface disturbance extent of two historic releases, including the well location access road.



Inspection Photos
Location Name: Croissant #4
Location ID: 331970



Photo 2. Photo taken from the well location.



Photo 3. Photo taken from the well location, facing Northwest. Photo illustrates an excavation around the wellhead that has not been properly contoured.

Contractor on location stated fill material will be imported from a local source.

Inspection Photos
Location Name: Croissant #4
Location ID: 331970



Photo 4. Photo taken from an area of the excavation, facing South. Photo illustrates the excavation area was seeded but with introduced species that is not reflective of reference area species.



Photo 5. Photo illustrates an introduced grass species, Crested wheatgrass, that was planted.



Inspection Photos
Location Name: Croissant #4
Location ID: 331970



Photo 6. Reference vegetation photo taken west of the wellhead, facing North.
Photo illustrates native perennial grasses.



Inspection Photos
Location Name: Croissant #4
Location ID: 331970



Photo 7. Photo taken from southern excavation extent, facing East. Photo illustrates vegetation has established but it's not reflective of reference area vegetation.



Photo 8. Photo taken from southern excavation extent, facing North. See comments under Photo 7.



Inspection Photos
Location Name: Croissant #4
Location ID: 331970



Photo 9. Photo taken from southern excavation extent, facing West. Photo illustrates the western excavation area is dominated by weedy, annual vegetation, which needs to be managed.



Photo 10. Photo taken from southern excavation extent, facing South. Photo illustrates the access road needs to be reclaimed per Rule 1004.