

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2023

Submitted Date:

08/29/2023

Document Number:

707800572

FIELD INSPECTION FORM

Loc ID 334663 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 18 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271021	WELL	PR	06/06/2012	GW	045-09813	S.PARACHUTE FEDERAL 30-14	PR
278446	WELL	PR	11/01/2020	GW	045-10882	FEDERAL 30-1BB (PA30)	PR
284146	WELL	SI	06/01/2022	GW	045-12095	FEDERAL 20-13 (PA30)	PR
423625	WELL	PR	02/13/2012	GW	045-20780	Federal 29-4 (PA-30)	PR
423631	WELL	PR	02/13/2012	GW	045-20781	Federal Smith 30-2 (PA-30)	PR
423632	WELL	PR	02/13/2012	GW	045-20782	Federal Smith 19-15 (PA-30)	PR
423634	WELL	PR	02/13/2012	GW	045-20783	Federal 29-4BB (PA-30)	PR
423635	WELL	PR	02/13/2012	GW	045-20784	Federal 29-4C (PA-30)	PR
423636	WELL	PR	02/13/2012	GW	045-20785	Federal 20-13A (PA-30)	PR
423637	WELL	PR	02/28/2012	GW	045-20786	Federal 29-4A (PA-30)	PR
423641	WELL	PR	02/15/2012	GW	045-20787	Federal 19-16BB (PA-30)	PR

General Comment:

ECMC Inspection Report Summary

On Monday 8/28/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus PA 30, at Location # 334663 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

C/A (battery signage) has been completed from previous inspection.

During this inspection the following compliance issues were observed:

1. Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.
 2. Random debris
 3. Chemical containment full of fluid not sufficient to contain possible spill
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<u>911/970-285-2615</u>		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	OTHER		
Comment:	Chemical containment full of fluid not sufficient to contain possible spill		
Corrective Action:	Evacuate fluids in containments to provide adequate space in case of a spill	Date:	<u>10/06/2023</u>
Type	OTHER		
Comment:	Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.		
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.	Date:	<u>10/06/2023</u>
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	<u>10/06/2023</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:		corrective date
Type: Gas Meter Run	# 12	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 11	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Chemical tank in plastic containment	
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 11	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 11	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	271021	Type:	WELL	API Number:	045-09813	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	278446	Type:	WELL	API Number:	045-10882	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	284146	Type:	WELL	API Number:	045-12095	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	423625	Type:	WELL	API Number:	045-20780	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	423631	Type:	WELL	API Number:	045-20781	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	423632	Type:	WELL	API Number:	045-20782	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	423634	Type:	WELL	API Number:	045-20783	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	423635	Type:	WELL	API Number:	045-20784	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID: 423636 Type: WELL API Number: 045-20785 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 423637 Type: WELL API Number: 045-20786 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 423641 Type: WELL API Number: 045-20787 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
Berms						
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800581	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238047