



Photo #1 Sign at Wellhead.

Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

Photo #2 photo of well. Tank is behind photo.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #3 wellhead. Flowline on right of photo goes to the Tank. The flowline on the left goes to the South.**



Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #4 Off location flowline. Flowline heads off to the south and below ground.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #5 Close up of wellhead. Flowline was a shallow burry.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #6 Tank with subsurface flowline to well.**



Photo #7 Scat on location.



Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel



Inspection Photos  
well 057-06281  
Inspection  
Date:8/18/2023

All Photos taken  
by Kris Neidel

**Photo #8 photo showing proximity of tank to well.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources