

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 8/22/2023



SE Corner of Location – Photo #06053



SW Corner of Location – Photo #06054

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 8/22/2023



East Side of Location – Photo #06055



Wellheads – Photo #06056

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 8/22/2023



Separators – Photo #06058



Tank Battery – Photo #06057

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 8/22/2023



Location Lacks Stabilization – Photo #06059



Insufficient Erosion Control on East Berm/Cut Slope – Photo #06061

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 8/22/2023



Insufficient Erosion Control on East Berm/Cut Slope – Photo #06062



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #06060