

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location ID: 334743

Date: 8/23/2023



SW Entrance to Location – Photo #06071



SE Corner of Location – Photo #06072

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location ID: 334743

Date: 8/23/2023



NW Corner of Location – Photo #06073



Wellheads – Photo #06074

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location ID: 334743

Date: 8/23/2023



Aug 23, 2023 at 10:52:48
Parachute CO 81635
United States



Aug 23, 2023 at 10:53:01
Parachute CO 81635
United States

Separators – Photo #06075

Tank Battery – Photo #06076

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location ID: 334743

Date: 8/23/2023



Location Lacks Stabilization – Photo #06077



Insufficient Erosion Control/Sediment Run-On to Location – Photo #06079

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location ID: 334743

Date: 8/23/2023



Insufficient Erosion Control – Photo #06080



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06081**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location ID: 334743

Date: 8/23/2023



**Degradation of Access Road/Insufficient Erosion Control –
Photo #06084**

**Degradation of Access Road/Insufficient Erosion Control –
Photo #06087**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/35SESE

Location ID: 334743

Date: 8/23/2023



**Degradation of Access Road/Insufficient Erosion Control –
Photo #06085**

**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06086**