

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2023

Submitted Date:

09/05/2023

Document Number:

708901558

FIELD INSPECTION FORMLoc ID 335192 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261879	WELL	PR	06/02/2002	GW	045-07993	LANGSTAFF RWF324-16	PR
281754	WELL	PR	12/02/2005	GW	045-11528	LANGSTAFF RWF 523-16	PR
281755	WELL	PR	12/02/2005	GW	045-11529	LANGSTAFF RWF 424-16	PR

General Comment:**CECMC Inspection Report Summary**

On 09/05/2023 at approximately 10:50 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC LANGSTAFF RWF324-16 Pad.
Location # 335192 in Garfield County Colorado.

Please refer to inspection 707800017 conducted on 12/15/2022, previous corrective action has been completed.

Location is within High Priority/Density Habitat areas.

Location is approximately 478 yards from a creek/drainage that contributes to the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Unmarked deadman with a CA date of 09/19/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Remote location/Split pad - Wellheads only - Tank battery & production separators are located on the LANGSTAFF RMV 12-16 pad, location # 335188.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	No tank battery on location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Hog panels			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Deadman # & Marked	# 4			
Comment:	3 deadman marked & 1 unmarked deadman			
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.			Date: 09/19/2023
Type: Bradenhead	# 3			
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:				Date:
Type: Plunger Lift	# 3			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Venting:				
Yes/No	NO			

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	261879	Type:	WELL	API Number:	045-07993	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	281754	Type:	WELL	API Number:	045-11528	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	281755	Type:	WELL	API Number:	045-11529	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse in a few small areas
Ditches						
		Ditches				
		Compaction				Light compaction in some sections
		Culverts				
Compaction						
Sediment Traps						
		Gravel				Sparse

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Equipment for observed compliance issue.	smelserw	09/05/2023
Remote location/Split pad - Wellheads only - Tank battery & production separators are located on the LANGSTAFF RMV 12-16 pad, location # 335188.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901559	Inspection 708901558 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6241785
708901561	Inspection 708901558 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6241786