

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2023

Submitted Date:

08/23/2023

Document Number:

707800550

**FIELD INSPECTION FORM**

Loc ID 334750 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
12 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283783	WELL	PR	05/01/2023	GW	045-12001	ENCANA 21-6BB(PF21)	PR
283785	WELL	PR	05/01/2023	GW	045-12000	ENCANA 21-6 (PF21)	PR
283787	WELL	PR	05/01/2023	GW	045-11999	ENCANA 21-5 (PF21)	PR
283790	WELL	PR	05/01/2023	GW	045-11998	ENCANA 21-3BB(PF21)	PR
288992	WELL	PR	05/01/2023	GW	045-13626	ENCANA FEDERAL 21-7BB (PF21)	PR
288993	WELL	PR	05/01/2023	GW	045-13625	ENCANA FEDERAL 21-7 (PF21)	PR

**General Comment:**

ECMC Inspection Report Summary  
 On Tuesday 8/22/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus PF 21, at Location # 334750 in Garfield county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

C/A (battery signage) from previous inspection document #'s 699803973 and 699804394 has been completed.

During this inspection the following compliance issues were observed:  
 1. Chemical containment full of fluid not sufficient to contain possible spill  
 2. Stored equipment on location has staining under equipment and next to it.  
 Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<a href="tel:9119702852615">911/970-285-2615</a>		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Stored equipment on location has staining under equipment and next to it.		
Corrective Action:	Remove stored equipment and stained material	Date:	<u>09/22/2023</u>
Type	OTHER		
Comment:	Chemical containment full of fluid not sufficient to contain possible spill		
Corrective Action:	Evacuate fluids in containments to provide adequate space in case of a spill	Date:	<u>09/22/2023</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	283783	Type:	WELL	API Number:	045-12001	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	283785	Type:	WELL	API Number:	045-12000	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	283787	Type:	WELL	API Number:	045-11999	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	283790	Type:	WELL	API Number:	045-11998	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	288992	Type:	WELL	API Number:	045-13626	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	288993	Type:	WELL	API Number:	045-13625	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
		Ditches				
		Culverts				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403516738	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238051">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238051</a>
707800560	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238035">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238035</a>