

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/25/2023

Document Number:

712700579

**FIELD INSPECTION FORM**Loc ID 333659 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273469	WELL	PR	08/24/2004	CBM	067-08968	PICCOLI A 2	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Locked gate, 2C40 key.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Present			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	Pumpjack weights on ground. See Photo #5.			
Corrective Action:	Remove unused equipment per Rule 606, or return to service.			Date: 10/04/2023
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Cattle panel			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Metal mesh			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panel enclosure around tank, separators, meterhouses, and telemetry.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Gas Meter Run	# 2			corrective date
Comment:	3" lines from separator to meterhouses. Calibration date 7/12/2023.			

Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked	# 2				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	Wellhead				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 3				
Comment:	3" lines from wellhead to separator.				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Electrical box				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Telemetry				
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:	Electric motor				
Corrective Action:				Date:	
Type: Bradenhead	# 3				
Comment:	PVC access				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.175040,-107.789040	
Comment:						
Corrective Action:					Date:	

Paint

Inspector Name: Pattillo, Curtis

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Wells Served By Facilities Above**

API Number
067-09307
067-09366

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	273469	Type:	WELL	API Number:	067-08968	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	06/01/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Ditches	Pass			
Compaction	Pass					
Berms	Pass	Culverts	Pass			
Gravel	Pass					
Check Dams	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403519638	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240945">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240945</a>
712700585	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240926">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240926</a>