

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2023

Submitted Date:

08/28/2023

Document Number:

712700588

FIELD INSPECTION FORMLoc ID 325780 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|--------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | sjninspections@ikavenergy.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 215371 | WELL | PR | 04/17/1989 | CBM | 067-06976 | BARNES-LEIDY 1 | PR |

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location

| | | | |
|--------------------|------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Locked gate, 2C40 key. | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|---------|-------------|
| Emergency Contact Number: | | |
| Comment: | Present | |
| Corrective Action: | | Date: _____ |

| | | |
|---------------------------|---|------------------|
| Good Housekeeping: | | |
| Type | WEEDS | |
| Comment: | Shrubs growing around pumpjack. See Photos #3 & #4. | |
| Corrective Action: | Remove weeds and all combustible material within 25' of equipment per Rule 610.k. | Date: 09/06/2023 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | |
|--------------------|--|-------|
| Fencing/: | | |
| Type | SEPARATOR | |
| Comment: | Cattle panel enclosure around separator and meterhouse. | |
| Corrective Action: | | Date: |
| Type | PUMP JACK | |
| Comment: | 6-ft chainlink. | |
| Corrective Action: | | Date: |
| Type | WELLHEAD | |
| Comment: | Cattle panel enclosure around wellhead, pumpjack, telemetry, and lube oil container. | |
| Corrective Action: | | Date: |
| Type | OTHER | |
| Comment: | Telemetry, cattle panel. | |
| Corrective Action: | | Date: |

| | | | | | |
|---------------------------------|--|--|--|-----------------|--|
| Equipment: | | | | corrective date | |
| Type: Gas Meter Run | # 2 | | | | |
| Comment: | 3" line from wellhead to separator. 1" line from separator to prime mover. | | | | |
| Corrective Action: | | | | Date: | |
| Type: Pump Jack | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Gas Meter Run | # 1 | | | | |
| Comment: | 2" line from separator to meterhouse. Calibration date 8/21/2023. | | | | |
| Corrective Action: | | | | Date: | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | PVC access | | | | |
| Corrective Action: | | | | Date: | |
| Type: Ancillary equipment | # 1 | | | | |
| Comment: | Wellhead | | | | |
| Corrective Action: | | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Prime Mover | # 1 | | | | |
| Comment: | Natural gas motor | | | | |
| Corrective Action: | | | | Date: | |
| Type: Bird Protectors | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Vertical Heated Separator | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | 37.136420,-107.801180 |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-------------------------|----------------------------|------------------------|-------------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 215371 | Type: | WELL | API Number: | 067-06976 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 05/24/2023 | Annual Brhd Completed? | Yes | | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 7 | Fluid Type: | | | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Berms | Pass | Ditches | Pass | Material Handling And Spill Prevention | Pass | Container within containment. |
| Waddles | Pass | Gravel | Pass | | | |
| Compaction | Pass | Culverts | Pass | | | |
| Gravel | Pass | | | | | |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403519640 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240947 |
| 712700593 | Well Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240929 |