

Inspection Photos

Loc: 308892

Operator: XTO ENERGY INC

Inspection Date: 9/28/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at the beginning of the access road. Stormwater run-on has caused erosion along the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308892 | Date: 9/28/2023

Inspection Photos



Photo 2. Facing southwest along the access road. There is an erosion channel down the road.



Inspection Photos



Photo 3. Facing southwest along the access road. Stormwater is cutting into the side of the road in this area. BMPs need to be installed to prevent further erosion.



Inspection Photos



Photo 4. Stormwater run-on from the road that switches back above is causing erosion in this area along the road cut slope.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308892 | Date: 9/28/2023

Inspection Photos



Photo 5. There is sediment accumulation along this rip/rap outlet which needs maintenance (shoveled/cleaned out).



Inspection Photos



Photo 6. Facing northwest along the access road. There is erosion along the road side at this area. BMPs need to be installed to prevent further erosion.



Inspection Photos



Photo 7. Facing west along the road. The rock check dams have filled in with gravel and sediment.



Inspection Photos



Photo 8. Further along the road facing west.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308892 | Date: 9/28/2023

Inspection Photos



Photo 9. There is sediment accumulation along this rip/rap check dams which needs maintenance (shoveled/cleaned out).



Inspection Photos



Photo 10. Facing west toward the remainder of the road to the abandoned wellsite on top of the ridge.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308892 | Date: 9/28/2023

Inspection Photos



Photo 11. Facing west at the location.



Inspection Photos



Photo 12. Facing south at the location.



Inspection Photos



Photo 13. Facing north at the location.

